


## Turning toolholders external



Right hand shown

Unit mm



Application	Insert	Dimensions						Master insert
		Order code	Part code	h	b	l1	f1	
72.5°	11	J145.12.12.80.11.1	SWBN 1212 F11	12	12	80	16	VBMT 1103
		J145.16.16.100.11.1	SWBN 1616 H11	16	16	100	20	VBMT 1103
		J145.20.20.125.11.1	SWBN 2020 K11	20	20	125	25	VBMT 1103
	16	J145.20.20.125.16.1	SWBN 2020 K16	20	20	125	25	VBMT 1604
		J145.25.25.150.16.1	SWBN 2525 M16	25	25	150	32	VBMT 1604
		J145.32.32.170.16.1	SWBN 3232 P16	32	32	170	40	VBMT 1604

Spare parts, parts included in delivery

Designation	Clamp	Clamping screw	Wrench	Shim	Shim screw	Spring
1212..		CS95 (M2,5)	W95.1 (T8)			
1616..		CS95 (M2,5)	W95.1 (T8)			
VBMT 11..		CS95 (M2,5)	W95.1 (T8)			
VBMT 16..		CS96 (M3,5)	W96.1 (T15)	SVB.16	SS101 (M5)	

Please check availability in current price and stock list